

Case Study







As part of the main entry lobby refurbishment to the 442 St Kilda Road apartment building, record Automatic Doors supplied and installed three STA 20 automatic sliding doors. Two of the operators were mounted in the ceiling space with record combination sensors flush mounted within the ceiling finishes.



Case Study







Case Study







Case Study

